



REPLACEMENT FOR
145/146 '94-'99




REPLACEMENT FOR
147 '00-'03



AF

667-1401
SIDE LAMP
PCS CFT

W5W TBA

667-1110-RD-LD-EM
HEAD LAMP
RD:
R MHL829 LD: R LPG281
L 468261950 L LPG282
4PCS 4.95CFT L 710301186203

H7/H7/H1/H6W

667-1403PXUE-C
SIDE LAMP
100PRS 1.57CFT

WY5W

667-1110-RD-LD-EM2
HEAD LAMP
R
L
4PCS 4.95CFT

H7/H7/H1/H6W

667-1601-AE
FRONT LAMP
R 106051
L 106050
20PCS 2.42CFT

PY21W

667-1901
TAIL LAMP
R
L 17631000
PCS CFT

P21/5W/P21W TBA

667-1903
TAIL LAMP
R
L
PCS CFT

P21/5W/P21W TBA

667-1403N-UE-Y
SIDE LAMP
F01101301
200PCS 1.53CFT

W5W

667-1301
BACK UP LAMP
R
L 17633000
PCS CFT

TBA

667-1303
BACK UP LAMP
R
L
PCS CFT

TBA

667-1403N-UE-C
SIDE LAMP
60679487
200PCS 1.53CFT

WY5W

667-2901-UE
REFLECTOR
R 501590
L 501600
PCS CFT

TBA


10/2000-10/2004

667-1303
BACK UP LAMP
R
L
PCS CFT

TBA

667-1403N-UE-C
SIDE LAMP
60679487
200PCS 1.53CFT

WY5W

667-2901-UE
REFLECTOR
R 501590
L 501600
PCS CFT

TBA